

Page 1 Of 2

Date Completed: \_\_\_\_\_ Failure Code: \_\_\_\_\_

Completed By : \_\_\_\_\_ Signature : \_\_\_\_\_

Accepted By : \_\_\_\_\_ Signature : \_\_\_\_\_

**\*\* Delay Codes Legend \*\***

W=Whse    C=CrSp    T=Tag    TL=Tool    P=Plan

**\*\* Record Time Daily \*\***

## Delays

Step	Job Scope	MN	DY	Safety and Additional Information
------	-----------	----	----	-----------------------------------

Emp No	Date	Hours	Code/Hrs
--------	------	-------	----------

1 COST TRACKER FOR TEI TO PROVIDE LABOR AND 1 1  
MATERIALS TO MODIFY AND REPAIR EXISTING  
PLANT VALVES, PER HOWARD HAMILTON.

```
*****
*****
```

SCOPE :

1- THIS WO. IS TO BE USED AS A MEANS OF TRACKING THE MATERIAL AND LABOR COSTS FOR TEI TO MODIFY AND REPAIR EXISTING VALVES.

2- COST NOT TO EXCEED \$5,720.28.

**\*\* IMPORTANT NOTICE \*\***

YOU ARE RESPONSIBLE FOR YOUR OWN SAFETY AND MUST ENSURE THAT THE REQUIRED PPE IS WORN FOR EVERY JOB YOU ARE DOING. IF YOU HAVE ANY QUESTIONS CONCERNING THE WORK RULES, SAFETY CODES, OR REQUIRED PPE, PLEASE CONTACT YOUR SUPERVISOR.

Job Feedback/Historical Notes:



**IP7\_032322**

## \*\* Work Order Parts List \*\*

Part No	Description	PO/Req/SIR	Date Due	U/M	Reqd	Commit	Issued/Rcvd
-----	-----	-----	-----	---	-----	-----	-----
1 18378	GLUE, CONTACT CEMENT	S 276436	03/09/04	GL	1	0	1
2 50064	TAPE, TEFLON	S 276436	03/09/04	RL	20	0	20
3 51728	ANTI-SEIZE, HI TEMP	S 276029	03/08/04	CN	16	0	16
4 DIRECT	REWORK BURNER COAL VALVES ON FORTY-NINE (49) BURNERS; INCLUD	04-45618-1	03/01/04	EA	1	0	1
5 DIRECT	REBUILD UNIT 2 BURNER ISOLATION VALVES AS PER MAINTENANCE RE	04-45618-2	04/26/04	EA	1	0	1

IP7\_032323